## 2016 - 3.1 - Default Asset Detail Photo Selection

All assets require an accurate elevation photo to be displayed on the Asset Detail Quick View page. Most assets display accurate and correct photo types. Some assets, however, are missing photographs, show inaccurate or outdated elevations, or display incorrect views.

241.24				S. and S.	Income Manuf	Bart Theorem		o 6
Ca 🛞 🔒 https://njta-it.bentl	ley.com/bridgedetail.aspx?ty	ype#0&asjid#13002						P-80 0 000
🖡 state.nj.us	Asset Details: MP E111	15 · ×			and some distant			An Monte Dissector
Elle Edit View Favorites Io	ols Help							
inspect tech	Main Collector	r Maintenance	Manager Administra	ition Help				Type Asset Name Here
Asset Details: MP E111.	15						O Show More Details	et Values 9 Show on Map O Create Report
Quick View Asset Info	Maintenance Sc	heduling Administr	ation					
Parent Asset: All District 6							Statement of the second	
Asset Name: MP E111.15 mg								TH2
Asset Code: E111150					Photo	is of deck joint		H.
Asset Type: Bridges					FIIOLO	is of deck joint,	and the second second second	- If an carry in the second
Carries: NSE & SNE ROADWAYS & MEDIAN							and the second se	
Over Rdwys: MILE E111 U-TURN COUNTY ROAD ERIE RAILROAD CO. CROXTON YARD (CONRAIL) ERIE PATERSON MAINLINE (N.J. 1					NJ not ele	vation	And the second se	111
Utilities: 2 @ 72' WATER; 4KV ELEC. 4 DUCTS-UG. FIBER OPTICS UNDER MEDIAN Total Leads: 23007							and the second se	<u>二</u> 書
Year Built: 1951							and a state of the	I I I I I I I I I I I I I I I I I I I
Contract Bit, Number: 54								1
Modified Contract No: R-951	R-1347							E BALL CONTRACTOR
Additional Information: Deck R-1269, R-1308, R-1347 WIDE R-1223, R-1268, R-1172-1 (Dr Contracts: Approach Resurfaci 003, County Code: 017 - Hud 004, Place Code: 66570 - See	Repair Contracts: R-114 NING, R-1357, T100.29 rainage), R-1418, R-1357 ing Contracts: T200.249 son raucus contracts: C200.249 contracts: C200.249 co	, R-260, R-290, R-293, F 8 (2015) Joint Repair / R , R-1296 (Fiber Optics),	2-309, R-329, R-341, R-352 eplacement Contracts: R-13 [100.298 (2015: rep inlets)   [100.298 (2015: rep inlets)	, R-360, R-372, R-432, R-48 57, T100.296 (2015) Misc. S Median Contracts: R-46 (Orig	, R-499, R-526, R-546, R-689, R ructural Repair Contracts: #316 ( : Median), R-951 (42' Wall) Barri	748. R-800, R-883, R-926, R-957, R-1004, R-1034, R- Backwall Buttressels, R-637, R-656-1, R-711, R-713 (§ er Contracts: Paint Contracts: R-50A, R-369 Signing Co	1097, R-1140, 53), R-987, R-114 ontracts: GR	
009. Location: 1.5 MI NORTH	OF INTER 15W							
045. Number of Main Spans: 046. Number of Approach Sc	014							
Maintenance & Jurisdictiona	Agreement:							
Bridge Security Features:								
092AA. Requires Fracture Cr	ritical Inspection ?: N/A							
092BA. Requires Underwater	r Inspection?: N/A							
Is NJDOT Courtesy Bridge:								
Open Reports								
Inspection Date	Last Revision	Asset Code	Owner	Asset Type	Road Carried	Feature Crossed	Submitt	ed To Status
05/26/2016	06/24/2016	E111150	McMullan, Dan	Bridges	NSE / SNE Roadways	Erie Viaduct (NJ Transit / Conrail)(N	MP115 U-Turn)	In progress 😿 🕨
Scheduling	n asset							
the beneduling identicities and								
A 16 1 1 4 1 4				8.040	and in the second role mapping the	the of the spirit,		00 - 8
(=) 🕒 https://njta-it.benti	ley.com/bridgedetail.aspx?ty	pen0&as_ida12807						P-80 0 000
2 state.ni.us	Asset Details: MP 160.0	55 - B ×	Are 2 - 4	y +				
File Edit View Favorites To	ols Help							
for for for share for	11-F							
inspect ech	Main Collector	r Maintenance	Manager Administra	tion Help				Type Asset Name Here



Whenever outdated, missing or incorrect default photograph is encountered, users shall select one of the most recent elevation photos using the following steps:

- Category All
  Photo 1
  P
- 1. Access Photos from Pics/Files in Report Forms. Find the most recent elevation photo. Select the Set as Default Image button.

2. Upon existing the report, users will be able to see the newly selected default photograph on the Asset Detail Page.

