

Attachment 2018-2.2

Inspectors now have the ability to submit the report directly to Engineering, bypassing the Submitted to Maintenance stage. This is only to be used upon liaison direction that a reported defect is beyond resources of the Maintenance Department.

This is to be used when the Beyond Resources of Maintenance Department checkbox has been checked.

Created | None Assigned

Send email notifications when workflow stage is changed

Type: Inadequate Clearance

Structure Name:

Maintenance District:

Created By: Hall, Suzanne

Updated By:

Observed By:

Type of Damage: Inadequate Under clearance required posting over Route 46

Description: The vertical clearance measured over the NB left lane of Route 46 is 14' 9" posting since it is below the required 14'-9".
We recommend NJDOT be notified to install clearance postings.
THIS CANNOT BE PERFORMED BY MAINTENANCE FORCES.

☒ Beyond Resources of Maintenance Department

Maintenance Remarks:

Engineering Remarks: A letter was sent to NJDOT notifying them of the requirements to post the 9/10/2010.
A follow up email was submitted on xx.xx.xx.

Date Completed:

Files attached during current workflow stage:
There are no files attached

Workflow Stage Status: Pass

Workflow Stage: Submitted to Maintenance

Assign To: Submitted to Maintenance

Comments: Submitted to Engineering

Submit Close

/modal_pages/asset_task_workflow.aspx?ast_id=57250&type=1