


## 2019 - 1.0: New Contract History Form

Consultants are to review existing New Jersey Turnpike Authority contract information and populate the Contract History form as needed. Each contract is to be coded using one of the following contract types:

- Original Construction
- Major Rehabilitation
- Widening
- Interchange Improvement
- Superstructure Replacement
- Deck Repair
- Bridge Repair
- Roadway Resurfacing (Approach)
- Drainage Repair
- Specialized Structural Repair
- Painting
- Other

Sources for this information include the Authority's Card Files, which have been uploaded to Accellion for your reference.



Card Files are hand written cards, ordered by structure number, which list all contract work for a given bridge.

BR. OVER: WILDWOOD BLVD. (RT 47) BR # 3.9 "N"		DIST. # <b>78</b> SHEET <b>13</b>	BR. # 3.9 NORTH STATE SECTION
CONT. #			YE.
13-78 - GRAD. DRAW. PAINT & STRUCT. ORIG. CONSTR.			1954
198 - FURN. & ERECT STEEL BRIDGE RAILING			1954
84-887 - DK & SUBSTR. REPR. DK JOINTS, WATERPROF MMBR & BIT. CONC. OVERLY, CONC. BARR. CURB			1992
P100.08 - SOUTHERN BRIDGE DECK REPAIRS & RESURFACING			2007
<b>M-69. PAINTING</b>			<b>1986</b>
734. GUIDE RAIL IMPROV., APPROCH REPR.			1989
UNKNOWN • WILDWOOD BLVD. ROADWAY WK, GUIDE RAIL PROTECTION INSTALL AT PIER			03/04
84-1283. SUBSTRUCT. & SOFFIT REPS - S / M.P. 2.4 TO 128.2			2005
• APPROCHS PAVED; CONCRETE REPAIR DTL			2007
P100.074 - SOUTHERN BR. DK. REPAIRS & RESURF / M.P. 0 TO 113			2008
P100.410 Bridge Repairs & Resurfacing MP 0 - 126 (2018)			2017

Information from the Card Files should be entered into the Contract History form in chronological order (from oldest to newest), and include a detailed description of the type of work performed (original construction, bridge railing, painting, guide rail improvements, deck repair, substructure repair, etc.) entered in ALL CAPS.

The example below shows missing Descriptions of Work for noted contracts.

← → ↺ [https://njta-it.bentley.com/form.aspx?id=57934&type=1&fg\\_id=421&fm\\_id=6](https://njta-it.bentley.com/form.aspx?id=57934&type=1&fg_id=421&fm_id=6)

**NEW JERSEY TURNPIKE AUTHORITY**

**CONTRACT HISTORY**

NO. ROWS: 11 ▼

TYPE	CONTRACT NO.	DESCRIPTION OF WORK	YEAR	
Original Construction	13-78	ORIGINAL CONSTRUCTION	1954	
Other	198	BRIDGE RAILING	1954	
Painting	M-69	PAINTING	1986	
Other	734	GUIDE RAIL IMPROVEMENTS AND APPR. RES	1989	
Deck Repair	84-887	DK & SUBSTR. REPAIR, DK JOINTS, RESURFAC	1992	
Other	UNKNOWN	WILDWOOD BLVD ROADWAY WORK & PIER PF	2003/04	
Other	84-1283	SUBSTRUCTURE & SOFFIT REPAIR	2005	
Deck Repair	P100.008		2007	
Deck Repair	UNKNOWN	APPROACH RESURFACING & CONCRETE REP	2007	
Deck Repair	P100.074		2008	
Bridge Repair	P100.410		2017	

When detailed descriptions of the contract work are not included in the Card Files, refer to the “Additional Information” entry listed on the Asset Detail page for specific details. Details for Contract No P100.008 are listed and can be entered into the form. (Deck Repair, Joint Repair, etc)

← → ↻ 🔒 https://njta-it.bentley.com/bridgedetail.aspx?type=0&as\_id=14273 🔍 ☆ ⌵ 👤

**InspectTech**  
CONNECT Edition

Main Collector Maintenance Manager Administration  
Help

Type Asset Name Here...


Asset Details: MP 3.9N Show More Details Edit Asset Values Show on Map Create Report

Quick View Asset Info Files Maintenance Administration

**Parent Asset:** Parkway Bridge Group 1  
**Asset Name:** MP 3.9N 📷  
**Asset Code:** 360039N  
**Asset Type:** Bridges  
**Road Carried:** Parkway N  
**Features Intersected:** NJ Route 47 (Wildwood Blvd.)  
**Maintenance District:** GSP 1  
**Total Length:** 120'-0"  
**045. Number of Main Spans:** 002  
**046. Number of Approach Spans:** 000  
**Year Built:** 1954  
**Contract Blt. Number:** 13-78  
**Modified Contract No:**  
**Additional Information:** Deck Repair Contracts: 84-887, 84-1283(Soffit), P100.008  
Joint Repair / Replacement Contracts: 84-887, P100.008 Misc. Structural Repair  
Contracts: 84-887(Sub), 84-1283(Sub), P100.008(Waterproof) Median Contracts:  
Barrier Contracts: 198, 84-887 Paint Contracts: M-69 (1986) Signing Contracts: GR  
Contracts: 734, Unknown(2003/2004) **P200.127** Approach Resurfacing Contracts:  
734, Unknown(2007)  
**Contract Removed:**  
**Utilities:** None  
**000 Location:** 0.7 M SE OF RTS 47 & 10T

If contracts are listed on the Asset Detail page but are not included in the Card Files, or contracts are included in the Card Files but are not included in the “Additional Information” entry on the Asset Detail page; a request should be made to the Liaison to obtain the applicable As-Built contracts to verify the list.

In the examples above, Contract No. P200.127 is only listed on the Asset Detail Page, while Contract Nos. P100.074 and P100.410 are only listed in the Card Files.



Review of As-Built Contract No. P200.127 drawings verifies that approach guide rail work was performed at Structure No. 3.9N in 2009. Therefore, add this information to the Contract History form.

Since Contract P200.127 (2009) falls between P100.074 (2008) and P100.410 (2017) and currently there is not an option to add an intermediate row to the table you must add a blank row to the end and move all the existing information as needed.













← → ↻ [https://njta-it.bentley.com/form.aspx?id=57934&type=1&fg\\_id=421&fm\\_id=641](https://njta-it.bentley.com/form.aspx?id=57934&type=1&fg_id=421&fm_id=641)

**NEW JERSEY TURNPIKE AUTHORITY**













**CONTRACT HISTORY**

Note there are now 12 rows

TYPE	CONTRACT NO.	DESCRIPTION OF WORK	YEAR
Original Construction	13-78	ORIGINAL CONSTRUCTION	1954
Other	198	BRIDGE RAILING	1954
Painting	M-69	PAINTING	1986
Other	734	GUIDE RAIL IMPROVEMENTS AND APPR. RES	1989
Deck Repair	84-887	DK & SUBSTR. REPAIR, DK JOINTS, RESURFA	1992
Other	UNKNOWN	WILDWOOD BLVD ROADWAY WORK & PIER PF	2003/04
Other	84-1283	SUBSTRUCTURE & SOFFIT REPAIR	2005
Deck Repair	P100.008		2007
Deck Repair	UNKNOWN	APPROACH RESURFACING & CONCRETE REP	2007
Deck Repair	P100.074		2008
Bridge Repair	P100.410		2017

NEW JERSEY TURNPIKE AUTHORITY				
CONTRACT HISTORY				
TYPE	CONTRACT NO.	DESCRIPTION OF WORK	YEAR	
NO. ROWS: 12 ▼				
Original Construction	13-78	ORIGINAL CONSTRUCTION	1954	
Other	198	BRIDGE RAILING	1954	
Painting	M-69	PAINTING	1986	
Other	734	GUIDE RAIL IMPROVEMENTS AND APPR. RES	1989	
Deck Repair	84-887	DK & SUBSTR. REPAIR, DK JOINTS, RESURFA	1992	
Other	UNKNOWN	WILDWOOD BLVD ROADWAY WORK & PIER PF	2003/04	
Other	84-1283	SUBSTRUCTURE & SOFFIT REPAIR	2005	
Deck Repair	P100.008		2007	
Deck Repair	UNKNOWN	APPROACH RESURFACING & CONCRETE REF	2007	
Deck Repair	P100.074		2008	
				
Bridge Repair	P100.410		2017	

P100.410 (2017)  
MOVED TO END

NEW JERSEY TURNPIKE AUTHORITY				
CONTRACT HISTORY				
TYPE	CONTRACT NO.	DESCRIPTION OF WORK	YEAR	
NO. ROWS: 12 ▼				
Original Construction	13-78	ORIGINAL CONSTRUCTION	1954	
Other	198	BRIDGE RAILING	1954	
Painting	M-69	PAINTING	1986	
Other	734	GUIDE RAIL IMPROVEMENTS AND APPR. RES	1989	
Deck Repair	84-887	DK & SUBSTR. REPAIR, DK JOINTS, RESURFA	1992	
Other	UNKNOWN	WILDWOOD BLVD ROADWAY WORK & PIER PF	2003/04	
Other	84-1283	SUBSTRUCTURE & SOFFIT REPAIR	2005	
Deck Repair	P100.008		2007	
Deck Repair	UNKNOWN	APPROACH RESURFACING & CONCRETE REF	2007	
Deck Repair	P100.074		2008	
Other	P200.127	APPROACH GUIDE RAIL	2009	
Bridge Repair	P100.410		2017	

INFORMATION  
FOR P200.127  
ADDED

Similar detailed review of As-Built Contract No. P100.074 drawings indicates the performance of anchor bolt replacement in the precast barrier on Structure No. 3.9N.

Similar detailed review of As-Built Contract No. P100.410 indicates the performance of joint reconstruction (1P), underdeck spall coating, and substructure spall repair at Structure No. 3.9N.

ESTIMATED QUANTITIES											
ITEM NO.	UNIT CODE	ITEM	UNIT	PRE/POST STAGE	STAGE 1	STAGE 2	STAGE 3	STAGE 4	STAGE 5	PLAN	AS-BUILT
QUANTITIES											
4	302-0062	MEMBRANE WATERPROOFING	S.Y.	0	60	80	0	0	0	140	
6	302-0064	TACK COAT	GAL.	0	4	5	0	0	0	9	
10	302-0071	POLYMERIZED JOINT ADHESIVE	L.F.	0	0	36	0	0	0	360	
11	302-0073	HOT MIX ASPHALT 12.5MM SURFACE COURSE	TON	0	15	20	0	0	0	35	
13	302-N0002	TEMPORARY SURFACING	TON	2	0	0	0	0	0	2	
16	305-0031	PAVEMENT REMOVAL, VARIABLE DEPTH	S.Y.	0	40	50	0	0	0	90	
17	306-0001	MILLED RUMBLE STRIP	L.F.	32	0	0	0	0	0	32	
35	417-0009	REMOVAL OF EXISTING SURFACING	S.Y.	0	60	80	0	0	0	140	
37	417-0016	SPALL REPAIR, TYPE 5	S.F.	0	100	15	0	0	0	250	
39	417-0020	JOINT RECONSTRUCTION, TYPE 1	L.F.	0	20	25	0	0	0	45	
40	417-0021	JOINT SEAL REPLACEMENT, TYPE 1	L.F.	0	23	28	0	0	0	51	
41	417-0033	REPAIR UNDERDECK SPALLS (CLEAN AND COAT)	S.F.	0	0	0	0	0	10	10	
42	417-0035	JOINT RECONSTRUCTION, TYPE 1	L.F.	0	40	52	0	0	0	92	
53	418-0001	REPAIR SPALLED CONCRETE, TYPE 1 - ABUTMENT	S.F.	0	0	0	50	30	0	80	
87	516-0009	TRAFFIC STRIPES, LONG-LIFE, THERMOPLASTIC	L.F.	0	40	30	0	0	0	70	
103	801-N0001	INSTALLATION, MAINTENANCE, AND REMOVAL OF LANE CLOSING	EACH	4	1	1	0	0	0	6	

These missing descriptions of work should be added to the Contract History form.

https://njta-it.bentley.com/form.aspx?id=57934&type=1&lg\_id=421&fm\_id=641

### NEW JERSEY TURNPIKE AUTHORITY

#### CONTRACT HISTORY

NO. ROWS: 12 ▼

Original Construction	13-78	ORIGINAL CONSTRUCTION	1954	
Other	198	BRIDGE RAILING	1954	
Painting	M-69	PAINTING	1986	
Other	734	GUIDE RAIL IMPROVEMENTS AND APPR. RES	1989	
Deck Repair	84-887	DK & SUBSTR. REPAIR, DK JOINTS, RESURFA	1992	
Other	UNKNOWN	WILDWOOD BLVD ROADWAY WORK & PIER PF	2003/04	
Other	84-1283	SUBSTRUCTURE & SOFFIT REPAIR	2005	
Deck Repair	P100.008	DECK REPAIR, JOINT REPAIR, WATERPROOFII	2007	
Deck Repair	UNKNOWN	APPROACH RESURFACING & CONCRETE REF	2007	
Deck Repair	P100.074	AB REPLACEMENT IN BARRIER	2008	
Other	P200.127	APPROACH GUIDE RAIL	2009	
Bridge Repair	P100.410	JOINT RECONSTRUCTION (1P), SOFFIT AND A	2017	